

# Huntsville Golf Course Headwater Tributaries flowing into the Huntsville Creek Watershed



# Figure 1

Headwaters of unnamed tributary (UNT) through Huntsville Golf Club, further upstream it passes under 118





## Figure 2

More headwaters  
downstream from Fig. 1





# Figure 3

Headwaters entering  
UNT on golf club near  
Route 118





# Figure 4

Downstream view of UNT  
passing further into golf  
club.





# Figure 5

Upstream view of UNT  
meandering through golf  
club.





## Figure 6

Downstream view of UNT entering concrete pipe under path in golf club.





# Figure 7

Downstream view of UNT passing through concrete pipe and then under bridge





# Figure 8

Upstream view of pipe in  
Fig. 7, slightly broken and  
filled with sediment

**41.320072, -76.015741**





## Figure 9

Downstream view of UNT in Fig. 3-8: Further downstream, passing through two concrete pipes, with one HDPE pipe for high flow






# Figure 10

Photo of stick-building  
caddisfly in UNT in Fig. 9

Further upstream from  
Fig. 9, a footpath  
obstructs flow.

**41.322277, -76.010726**



# Figure 11

Two ponds on one side of cart path, not part of golf club property, all drain toward Rte. 115

Winged culvert carries small UNT from here to second pond





# Figure 12

Second pond near golf club, connected to first with winged culvert



# Figure 13

Third pond on other side  
of cart path with drain  
from Fig. 13, also drains  
to Rte. 115





# Figure 14

Downstream view of  
drainage from pond in  
Fig. 12 to pond in Fig. 13





# Figure 15

Upstream view of HDPE pipe in Fig. 14

**41.314697, -76.010623**





# Figure 16

Abandoned barn on golf club with UNT and headwaters that drain toward Rte. 115





# Figure 17

Large pond near Fig. 16  
with drainage pump that  
carries excess flow to  
other wetlands closer to  
Rte. 115





# Figure 18

View of pump in pond in  
Fig. 17 that carries  
excess flow





# Figure 19

Another pond near Fig.  
16-19, also drains toward  
Rte. 115

**41.313735, -76.013980**





## Figure 20

Downstream view of HDPE pipe that carries excess flow from pond in Fig. 17-18 into wetlands that drain toward Rte. 115





# Figure 21

Downstream view of  
HDPE pipe in Fig. 20 and  
the golf club's dog





## Figure 22

View of HDPE pipe on other side of cart path that receives the pump used in the pond in Fig. 17-18

**41.312916, -76.012564**





## Figure 23

View of drop-in culvert  
that carries flow from  
wetlands in Fig. 20-21  
further toward Rte. 115

Full of sediment and  
prone to flooding in high  
flow events





# Figure 24

Downstream view of UNT  
from Fig. 23 after it  
passes under cart path  
(very entrance of GC)

Pipe is buried under soil  
and sediment

**41.310649, -76.011304**



## Figure 25

Upstream view of UNT further DS from Fig. 24 after it enters the GC

Manager commented that flow often crosses cart path, wondered how to improve





## Figure 26

Downstream view of UNT  
in Fig. 25 as it enters  
HDPE before being  
buried under golf club,  
then draining into  
wetlands closer to Rte.  
115



# Figure 27

Broad view of where UNT  
passes under golf club  
before entering wetlands

**41.310649, -76.011304**





## Figure 28

Downstream view of wetlands closest to Rte. 115, where most flow drains, including that from HDPE pipe on left

Flow enters concrete pipe before UNT flows into more wetlands





# Figure 29

Upstream of UNT in Fig. 28 as it meanders through lower golf club





# Figure 30

Downstream view of UNT  
in Fig. 28-29 after it  
passes under cart path



# Figure 31

Upstream view of unnamed tributary (UNT) in Fig. 30 as it passes through concrete pipe

Large scour with roughly 6" drop to UNT from pipe, does cause some bank erosion

**41.314844, -76.003628**

